



## NORTH ANDOVER COOLANT LINE REPAIR - NORTH ANDOVER, MA

### PROJECT INFO:

**OWNER:**

Wheelabrator Technologies

**ENGINEER:**

Methuen Industrial Services

**PROJECT VALUE:**

\$14,646.00

**TECHNOLOGIES/MATERIALS:**

16" Schedule 40 Steel Pipe

**PROJECT HIGHLIGHTS:**

Methuen Industrial Services received praise from the Wheelabrator Plant Manager for their quick and efficient response to an emergency situation.



### ADDITIONAL DETAILS

The Wheelabrator Plant Manager contacted Industrial Services to help him address a coolant line leak at the waste-to-energy facility in North Andover, MA. Methuen Industrial Services immediately dispatched a crew to the facility. The Methuen crew excavated the coolant line, removed the leaking section, replaced the 16" steel pipe, and repaved the work area. Here's the Plant Manager's response:

"Thank you for answering the call and jumping through hoops to get the coolant line repaired today. Your efforts were worth their weight in Gold. This is exactly why I call you guys when I'm in trouble."

Tim Shay  
Plant Manager  
Wheelabrator