



NORTH ANDOVER COOLANT LINE REPAIR - NORTH ANDOVER, MA

PROJECT INFO:

OWNER:

Wheelabrator Technologies

ENGINEER:

Methuen Industrial Services

PROJECT VALUE:

\$14,646.00

TECHNOLOGIES/MATERIALS:

16" Schedule 40 Steel Pipe

PROJECT HIGHLIGHTS:

Methuen Industrial Services received praise from the Wheelabrator Plant Manager for their quick and efficient response to an emergency situation.



ADDITIONAL DETAILS

The Wheelabrator Plant Manager contacted Industrial Services to help him address a coolant line leak at the waste-to-energy facility in North Andover, MA. Methuen Industrial Services immediately dispatched a crew to the facility. The Methuen crew excavated the coolant line, removed the leaking section, replaced the 16" steel pipe, and repaved the work area. Here's the Plant Manager's response:

"Thank you for answering the call and jumping through hoops to get the coolant line repaired today. Your efforts were worth their weight in Gold. This is exactly why I call you guys when I'm in trouble."

Tim Shay
Plant Manager
Wheelabrator